


UPGRADE CATALOG



TBM

Edition 15 - Aug 2023

Please select the model of your interest.



To order, please contact your local representative :
www.tbm.aero/support

TEBM 700 A

List of special offers:

- Landing gear actuator replacement p.5

List of available retrofits:

- Low LDG Door p.6
- LED taxi LDG lights p.7
- Barometric Valve installation 31,000 ft p.8
- Engine draining in exhaust stub p.9
- Modification of the oil drain breather hose p.10
- MC10 Oxygen mask with SmartMike p.11



TEBM 700 A

- Strobe and navigation lights update p.12
- LED Ice detection p.13
- Voice Alert Device P.14



LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Low landing gear door retrofit

Enjoy the latest enhancement for your TBM



Low landing gear door

Improves aerodynamics of the aircraft

Reduce drag

Better performances and Fuel saving

The main gear low door is made of honeycomb composite panel with glass/carbon-cloth

Validity

SN 1 to 684

SB Reference

SB70-228-52 R1

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Applicable Not applicable Already applied

Reference to order

OPT70K15300

T700H528004400001

T700H528004400101

Estimated labor hours

15 labor hours

Taxi & landing lights retrofit

Enjoy the latest enhancement for your TBM



Whelen LED Taxi/landing lights retrofit

Long life

High efficiency

Better resistance

Higher color temperature white

Better visibility during taxi


We provided you the only solution with a switch indicator light inside your cabin

Validity

SN 1 to 684

SB Reference

SB70-230-33



Applicable Not applicable Already applied

Reference to order


OPT70K23000
or OPT70K23001
(Check SB for validity)

Labor hours estimated

4 labor hours

Barometric valve 31,000 feet retrofit

Enjoy the latest enhancement for your TBM



Barometric valve 31,000 feet

Increases the flight ceiling from 30,000 feet to 31,000 feet

Allows the automatic supply and use of oxygen masks for the passengers.

This modification is valid for TBM 700A and TBM 700B already equipped with the gaseous oxygen system and P&WC SB14261 and 14308 applied.

Validity

SN 24, 36, 40 to 239

SB Reference


SB70-028-35 R01

Reference to order

OPT70K08235

Labor hours estimated


30 labor hours



Applicable Not applicable Already applied

Engine draining in exhaust stub retrofit

Enjoy the latest enhancement for your TBM




Engine draining in exhaust stub

Collection of the engine drains towards the R.H exhaust stub to avoid oxygen bottle area contamination hazard, burning oil in the exhaust.

Validity
SN 1 to 204, 206 to 215

SB Reference

SB70-097-71



Applicable Not applicable Already applied

Reference to order


OPT70K08071

Estimated labor hours

10 labor hours

Oil drain breather hose replacement

Enjoy the latest enhancement for your TBM




Oil drain breather hose

Avoid traces of grease inside engine cowling by hose replacement on which design has been improved

Validity
SN 1 to 345 with
OPT70K080-71 applied

SB Reference

SB70-141-71



Applicable Not applicable Already applied

Reference to order
T700A717003100100

Estimated labor hours

1.5 labor hours

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM equipped with MRA, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more "Darth Vader" breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 1 to SN 243 with option OPT70-35-001 (gaseous oxygen) & SN 244 to SN 433

SB Reference

SB70-279-35



Reference to order

MC10-02-123 - Qty. 2
&
1 kit: OPT70K27900

Estimated labor hours

30 labor hours

Applicable Not applicable Already applied

Strobe and navigation lights update

Benefit from the latest enhancement for your TBM



LED upgrade kit


The new strobes and navigation lights for TBM 700s and TBM 850s offer a longer life, higher efficiency, limited wear-and-tear, enhanced resistance and higher white color temperature.

Daher brings the latest available LED technology in an all-inclusive package.

Validity
From SN 1 to 684

SB Reference

SB70-296-33



Applicable Not applicable Already applied

Reference to order

T700A018404500100 (Red)
T700A018404500200 (Green)

Estimated labor hours

6 hours during an inspection;
7 hours when separate from
an inspection

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Voice Alert Device retrofit

Benefit from the latest enhancement for your TBM



Voice Alert Device


A major safety improvement replacing the A20 alert tone generator.

This new device replaces the existing audio tone warnings with spoken alerts: "Stall" "Landing gear" and "Overspeed".

Additionally, it provides the "Use oxygen mask" alert for cabin altitude.



Scan to see the video



Validity

From SN 1 to SN 433

SB Reference

SB70-263-31

Reference to order

Parts as per SB

Estimated labor hours

8 labor hours

Applicable Not applicable Already applied

TEBM 700 B

List of special offers:

- Landing gear actuator replacement p.17

List of available retrofits:

- Low LDG Door p.18
- LED taxi LDG lights p.19
- Barometric Valve installation 31,000 ft p.20
- Cabin heat deflector p.21
- Engine draining in exhaust stub p.22
- Modification of the oil drain breather hose p.23
- Chemical toilet cabinet p.24
- Pilot door handle p.25



TEBM 700 B

- MC10 Oxygen mask with SmartMike p.26
- Strobe and navigation light updates p.27
- LED Ice detection light p.28
- Voice Alert Device p.29



TBM 700

B

**SPECIAL
OFFER**

LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade

- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Low landing gear door retrofit

Enjoy the latest enhancement for your TBM



Low landing gear door

Improves aerodynamics of the aircraft

Reduce drag

Better performances and Fuel saving


The main gear low door is made of honeycomb composite panel with glass/carbon-cloth

Validity

SN 1 to 684

SB Reference

SB70-228-52 R1



Applicable Not applicable Already applied

Reference to order


OPT70K15300
T700H528004400001
T700H528004400101

Estimated labor hours

15 labor hours

Taxi & landing lights retrofit

Enjoy the latest enhancement for your TBM



Whelen LED Taxi/landing lights retrofit

Long life

High efficiency

Better resistance

Higher color temperature white

Better visibility during taxi


We provided you the only solution with a switch indicator light inside your cabin

Validity

SN 1 to 684

SB Reference

SB70-230-33



Reference to order

OPT70K23000
or OPT70K23001
(Check SB for validity)


Labor hours estimated

4 labor hours

Applicable Not applicable Already applied

Barometric valve 31,000 feet retrofit

Enjoy the latest enhancement for your TBM



Barometric valve 31,000 feet

Increases the flight ceiling from 30,000 feet to 31,000 feet

Allows the automatic supply and use of oxygen masks for the passengers.

This modification is valid for TBM 700A and TBM 700B already equipped with the gaseous oxygen system and P&WC SB14261 and 14308 applied.

Validity

SN 24, 36, 40 to 239

SB Reference


SB70-028-35 R01

Reference to order

OPT70K08235

Labor hours estimated


30 labor hours



Applicable Not applicable Already applied

Cabin heat deflector retrofit

Enjoy the latest enhancement for your TBM



Cabin heat deflector

The installation of a new deflector will optimize the hot airflow coming to the LH passenger's feet and will improve the cabin thermal comfort.

Validity

SN 126, 129, 137,
143-145, 148-433

SB Reference

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Reference to order

OPT70K13525


Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Engine draining in exhaust stub retrofit

Enjoy the latest enhancement for your TBM




Engine draining in exhaust stub

Collection of the engine drains towards the R.H exhaust stub to avoid oxygen bottle area contamination hazard, burning oil in the exhaust.

Validity
SN 1 to 204, 206 to 215

SB Reference

SB70-097-71



Applicable Not applicable Already applied

Reference to order



OPT70K08071

Estimated labor hours

10 labor hours

Oil drain breather hose replacement

Enjoy the latest enhancement for your TBM



Oil drain breather hose


Avoid traces of grease inside engine cowling by hose replacement on which design has been improved

Validity

SN 1 to 345 with
OPT70K080-71 applied

SB Reference

SB70-141-71



Reference to order

T700A717003100100

Estimated labor hours

1.5 labor hours

Applicable Not applicable Already applied

Chemical toilet cabinet option

Enjoy the latest enhancement for your TBM



Chemical toilet cabinet

This option consists of swapping-out the TBM's intermediate left seat with the toilet cabinet.

This system is used in the marine industry and is optimized for easy installation and servicing.

On ground, the toilet cabinet can be installed to replace the left middle seat.

In flight, the passengers will have a curtain to ensure privacy.


The kit includes the toilet, curtain and the POH option supplement.

Validity

TBM 700B equipped with MOD70-035-001 (Gaseous Oxygen), TBM 700C, TBM 850. SN 346 to 433

SB Reference

SB70-184-25
SB70-175-25



Reference to order

T700B252005100000
or T700G252002700000

Estimated labor hours

1 labor hours

Applicable Not applicable Already applied

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM equipped with MRA, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more "Darth Vader" breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 1 to SN 243 with option OPT70-35-001 (gaseous oxygen) & SN 244 to SN 433

SB Reference

SB70-279-35



Reference to order

MC10-02-123 - Qty. 2
&
1 kit: OPT70K27900

Estimated labor hours

30 labor hours

Applicable Not applicable Already applied

Strobe and navigation lights update

Benefit from the latest enhancement for your TBM



LED upgrade kit


The new strobes and navigation lights for TBM 700s and TBM 850s offer a longer life, higher efficiency, limited wear-and-tear, enhanced resistance and higher white color temperature.

Daher brings the latest available LED technology in an all-inclusive package.

Validity
From SN 1 to 684

SB Reference

SB70-296-33



Applicable Not applicable Already applied

Reference to order

T700A018404500100 (Red)
T700A018404500200 (Green)

Estimated labor hours

6 hours during an inspection;
7 hours when separate from
an inspection

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Voice Alert Device retrofit

Benefit from the latest enhancement for your TBM



Voice Alert Device

A major safety improvement replacing the A20 alert tone generator.

This new device replaces the existing audio tone warnings with spoken alerts: "Stall" "Landing gear" and "Overspeed".

Additionally, it provides the "Use oxygen mask" alert for cabin altitude.




Scan to see the video

Validity

From SN 1 to SN 433

SB Reference

SB70-263-31



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

8 labor hours

TEBM 700 C

List of special offers:

- Landing gear actuator replacement p.32

List of available retrofits:

- Low LDG Door p.33
- LED taxi LDG lights p.34
- Cabin heat deflector p.35
- Modification of the oil drain breather hose p.36
- Chemical toilet cabinet p.37
- Pilot door handle p.38
- MC10 Oxygen mask with SmartMike p.39



TBM 700 C

- Strobe and navigation light updates p.40
- LED Ice detection light p.41
- Voice Alert Device p.42



LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Low landing gear door retrofit

Enjoy the latest enhancement for your TBM



Low landing gear door

Improves aerodynamics of the aircraft

Reduce drag

Better performances and Fuel saving


The main gear low door is made of honeycomb composite panel with glass/carbon-cloth

Validity

SN 1 to 684

SB Reference

SB70-228-52 R1



Applicable Not applicable Already applied

Reference to order

OPT70K15300
T700H528004400001
T700H528004400101

Estimated labor hours

15 labor hours

Taxi & landing lights retrofit

Enjoy the latest enhancement for your TBM



Whelen LED Taxi/landing lights retrofit

Long life

High efficiency

Better resistance

Higher color temperature white

Better visibility during taxi


We provided you the only solution with a switch indicator light inside your cabin

Validity

SN 1 to 684

SB Reference

SB70-230-33



Applicable Not applicable Already applied

Reference to order


OPT70K23000
or OPT70K23001
(Check SB for validity)

Labor hours estimated

4 labor hours


Cabin heat deflector retrofit

Enjoy the latest enhancement for your TBM



Cabin heat deflector

The installation of a new deflector will optimize the hot airflow coming to the LH passenger's feet and will improve the cabin thermal comfort.



Validity

SN 126, 129, 137,
143-145, 148-433

SB Reference

Reference to order

OPT70K13525



Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Oil drain breather hose replacement

Enjoy the latest enhancement for your TBM



Oil drain breather hose


Avoid traces of grease inside engine cowling by hose replacement on which design has been improved

Validity

SN 1 to 345 with
OPT70K080-71 applied

SB Reference

SB70-141-71



Applicable Not applicable Already applied

Reference to order

T700A717003100100

Estimated labor hours

1.5 labor hours

Chemical toilet cabinet option

Enjoy the latest enhancement for your TBM



Chemical toilet cabinet

This option consists of swapping-out the TBM's intermediate left seat with the toilet cabinet.

This system is used in the marine industry and is optimized for easy installation and servicing.

On ground, the toilet cabinet can be installed to replace the left middle seat.

In flight, the passengers will have a curtain to ensure privacy.


The kit includes the toilet, curtain and the POH option supplement.

Validity

TBM 700B equipped with MOD70-035-001 (Gaseous Oxygen), TBM 700C, TBM 850. SN 346 to 433

SB Reference

SB70-184-25
SB70-175-25



Applicable Not applicable Already applied

Reference to order

T700B252005100000
or T700G252002700000

Estimated labor hours

1 labor hours

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM equipped with MRA, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more “Darth Vader” breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 1 to SN 243 with option OPT70-35-001 (gaseous oxygen) & SN 244 to SN 433

SB Reference

SB70-279-35



Reference to order

MC10-02-123 - Qty. 2
&
1 kit: OPT70K27900

Estimated labor hours

30 labor hours

Strobe and navigation lights update

Benefit from the latest enhancement for your TBM




LED upgrade kit

The new strobes and navigation lights for TBM 700s and TBM 850s offer a longer life, higher efficiency, limited wear-and-tear, enhanced resistance and higher white color temperature.

Daher brings the latest available LED technology in an all-inclusive package.

Validity
From SN 1 to 684

SB Reference
SB70-296-33



Applicable Not applicable Already applied

Reference to order

T700A018404500100 (Red)
T700A018404500200 (Green)

Estimated labor hours

6 hours during an inspection;
7 hours when separate from
an inspection

LED ice detection light


Benefit from the latest enhancement for your TBM



Ice detection light assembly

For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.



Validity

From SN 1 to 1157

SB Reference

SB70-297-33

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Applicable Not applicable Already applied

Voice Alert Device retrofit

Benefit from the latest enhancement for your TBM



Voice Alert Device


A major safety improvement replacing the A20 alert tone generator.

This new device replaces the existing audio tone warnings with spoken alerts: "Stall" "Landing gear" and "Overspeed".

Additionally, it provides the "Use oxygen mask" alert for cabin altitude.



Scan to see the video



Validity

From SN 1 to SN 433

SB Reference

SB70-263-31

Reference to order

Parts as per SB

Estimated labor hours

8 labor hours

Applicable Not applicable Already applied

TEBM 850

List of special offers:

- Landing gear actuator replacement p.45

List of available retrofits:

- Low LDG Door p.46
- LED taxi LDG lights p.47
- Cabin heat deflector p.48
- Chemical toilet cabinet p.49
- Exhaust stacks retrofit p.50
- Pilot door handle p.51
- MC10 Oxygen mask with SmartMike p.52



TBM 850

- Strobe and navigation light updates p.53
- LED Ice detection light p.54
- Voice Alert Device P.55



LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Low landing gear door retrofit

Enjoy the latest enhancement for your TBM



Low landing gear door

Improves aerodynamics of the aircraft

Reduce drag

Better performances and Fuel saving

The main gear low door is made of honeycomb composite panel with glass/carbon-cloth

Validity

SN 1 to 684

SB Reference

SB70-228-52 R1

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Applicable Not applicable Already applied

Reference to order

OPT70K15300

T700H528004400001

T700H528004400101

Estimated labor hours

15 labor hours

Taxi & landing lights retrofit

Enjoy the latest enhancement for your TBM



Whelen LED Taxi/landing lights retrofit

Long life

High efficiency

Better resistance

Higher color temperature white

Better visibility during taxi


We provided you the only solution with a switch indicator light inside your cabin

Validity

SN 1 to 684

SB Reference

SB70-230-33



Reference to order

OPT70K23000
or OPT70K23001
(Check SB for validity)


Labor hours estimated

4 labor hours

Applicable Not applicable Already applied

Cabin heat deflector retrofit

Enjoy the latest enhancement for your TBM



Cabin heat deflector

The installation of a new deflector will optimize the hot airflow coming to the LH passenger's feet and will improve the cabin thermal comfort.

Validity

SN 126, 129, 137,
143-145, 148-433

SB Reference

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Reference to order

OPT70K13525

Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Chemical toilet cabinet option

Enjoy the latest enhancement for your TBM



Chemical toilet cabinet

This option consists of swapping-out the TBM's intermediate left seat with the toilet cabinet.

This system is used in the marine industry and is optimized for easy installation and servicing.

On ground, the toilet cabinet can be installed to replace the left middle seat.

In flight, the passengers will have a curtain to ensure privacy.

The kit includes the toilet, curtain and the POH option supplement.

Validity

TBM 700B equipped with MOD70-035-001 (Gaseous Oxygen), TBM 700C, TBM 850. SN 346 to 433

SB Reference

SB70-184-25
SB70-175-25

940

960

A

930

B

TBM

910

C

900

850
G1000850
Legacy

Applicable Not applicable Already applied

Reference to order

T700B252005100000
or T700G252002700000

Estimated labor hours

1 labor hours

Exhaust stacks retrofit

Enjoy the latest enhancement for your TBM



Exhaust stacks


Replacement of the right and left hand exhaust stacks by “second generation ” exhausts which will significantly reduce the soot built-up without any performance alteration.

It is strongly recommended to include the oil drainage kit in addition to this modification.

That will avoid the presence of oily dirt on the lower fuselage skin

Validity

SN 346 to 570 equipped with MOD70-0202-78 or with OPT70K111-78



Reference to order

T700F781000500700 (R.H)
T700F781000500600 (L.H)

Estimated labor hours

6 labor hours

Applicable Not applicable Already applied

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM equipped with MRA, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more "Darth Vader" breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 1 to SN 243 with option OPT70-35-001 (gaseous oxygen) & SN 244 to SN 433

SB Reference

SB70-279-35



Applicable Not applicable Already applied

Reference to order

MC10-02-123 - Qty. 2
&
1 kit: OPT70K27900

Estimated labor hours

30 labor hours

Strobe and navigation lights update


Benefit from the latest enhancement for your TBM



LED upgrade kit

The new strobes and navigation lights for TBM 700s and TBM 850s offer a longer life, higher efficiency, limited wear-and-tear, enhanced resistance and higher white color temperature.

Daher brings the latest available LED technology in an all-inclusive package.



Validity

From SN 1 to 684

SB Reference

SB70-296-33

Reference to order

T700A018404500100 (Red)
T700A018404500200 (Green)

Estimated labor hours

6 hours during an inspection;
7 hours when separate from
an inspection

Applicable Not applicable Already applied

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Voice Alert Device retrofit

Benefit from the latest enhancement for your TBM




Voice Alert Device

A major safety improvement replacing the A20 alert tone generator.

This new device replaces the existing audio tone warnings with spoken alerts: "Stall" "Landing gear" and "Overspeed".

Additionally, it provides the "Use oxygen mask" alert for cabin altitude.




Scan to see the video

Validity

From SN 1 to SN 433

SB Reference

SB70-263-31



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

8 labor hours

TEBM **850** **+G1000**

List of special offers:

- Landing gear actuator replacement p.58

List of available retrofits:

- Low LDG Door p.59
- LED taxi LDG lights p.60
- Exhaust stacks retrofit p.61
- AOA/USP p.62
- AOA/ESP/USP p.63
- ESI 2000 p.64
- Garmin Flight Stream 210 p.65
- Chemical toilet cabinet p.66
- Privacy compartment chemical toilet p.67



TBM **850** **+G1000**

- Garmin G1000 NXi p.68
- Stick shaker p.69
- MD302 p.70
- Clothes hanger p.71
- Pilot door handle p.72
- MC10 SmartMike® p.73
- Strobe and navigation light updates p.74
- LED Ice detection light p.75
- Vapor cycle cooling system p.76



TBM
850
+G1000

SPECIAL
OFFER

LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3

Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Low landing gear door retrofit

Enjoy the latest enhancement for your TBM



Low landing gear door

Improves aerodynamics of the aircraft

Reduce drag

Better performances and Fuel saving

The main gear low door is made of honeycomb composite panel with glass/carbon-cloth

Validity

SN 1 to 684

SB Reference

SB70-228-52 R1

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Applicable Not applicable Already applied

Reference to order

OPT70K15300
T700H528004400001
T700H528004400101

Estimated labor hours

15 labor hours

Taxi & landing lights retrofit

Enjoy the latest enhancement for your TBM



Whelen LED Taxi/landing lights retrofit

Long life

High efficiency

Better resistance

Higher color temperature white

Better visibility during taxi


We provided you the only solution with a switch indicator light inside your cabin

Validity

SN 1 to 684

SB Reference

SB70-230-33



Applicable Not applicable Already applied

Reference to order

OPT70K23000
or OPT70K23001
(Check SB for validity)

Labor hours estimated

4 labor hours

Exhaust stacks retrofit

Enjoy the latest enhancement for your TBM




Exhaust stacks

Replacement of the right and left hand exhaust stacks by “second generation ” exhausts which will significantly reduce the soot built-up without any performance alteration.

It is strongly recommended to include the oil drainage kit in addition to this modification.

That will avoid the presence of oily dirt on the lower fuselage skin



Validity

SN 346 to 570 equipped with MOD70-0202-78 or with OPT70K111-78

Reference to order

T700F781000500700 (R.H)
T700F781000500600 (L.H)

Estimated labor hours

6 labor hours

Applicable Not applicable Already applied

AOA/USP Kit Retrofit

Enjoy flying your TBM with the New E-COPILOT[®] reducing pilot workload



AOA/USP Kit

What the AOA/USP kit bring ?

Enhanced safety with Under-Speed Protection

Modernized avionics with Angle of Attack (AOA) indication via a fully integrated system (PA ON)

Optimize and flight management and the landing approach

Go-around mode with autopilot engaged

940

960

A

Validity

SN 434 to 1105

930

B

Reference to order

Parts as per SB

910

C

SB Reference

SB-70-235-34

TBM

900

850*
G1000

850
Legacy

Estimated labor hours

35 labor hours

Applicable Not applicable Already applied

* if GSM 86 P/N 011-01904-03 and GSA P/N 011-00878-20 installed

AOA/USP/ESP Kit Retrofit

Enjoy flying your TBM with the New E-COPILOT[®] reducing pilot workload



AOA/USP/ESP Kit

Enhanced safety with Under-Speed Protection

Modernized avionics with Angle of Attack (AOA) indication via a fully integrated system


Optimize and flight management and the landing approach

Go-around mode with autopilot engaged

Prevent loss of control

Improve safety by deterring aircraft operation outside the desired flight envelope.

Electronic Stability & Protection is active only when the autopilot is disengaged.



Validity

SN 434 to 1105

Reference to order

Parts as per SB

SB Reference

SB-70-235-34

Estimated labor hours

35 labor hours

Applicable Not applicable Already applied

* if GSM 86 P/N 011-01904-03 and GSA P/N 011-00878-20 installed

Electronic Standby Indicator Model ESI-2000

Enjoy the latest enhancement for your TBM



ESI 2000

It replaces the three traditional electro-mechanical standby instruments and combines the information into a compact and easy to read 4" x 3" display.

It will continue to provide the pilot attitude, altitude and airspeed information from its own internal battery should aircraft primary electrical power be lost.

Validity

SN 434 to 633, 636 to 644

SB Reference


SB70-208-34

Reference to order

OPT70K14334

Estimated labor hours

25 labor hours



Applicable Not applicable Already applied

Garmin Flight Stream 210

Enjoy the latest enhancement available for your TBM



Compatible with:



Garmin Pilot



ForeFlight Mobile

FS 210 kit

Transfer of your flight plan from your Ipad to G1000

View of your flight info on your Ipad during flight

ADS-B traffic and weather data output to mobile device (US only)

Emergency AHRS included


Validity

SN 434 to 1105
(v15.11 required)

SN 1111 to 1158
except 1142 & 1157
(v6.6 required)

SB Reference

SB70-234-46



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

35 labor hours

Chemical toilet cabinet option

Enjoy the latest enhancement for your TBM



Chemical toilet cabinet

This option consists of swapping-out the TBM's intermediate left seat with the toilet cabinet.

This system is used in the marine industry and is optimized for easy installation and servicing.

On ground, the toilet cabinet can be installed to replace the left middle seat.

In flight, the passengers will have a curtain to ensure privacy.


The kit includes the toilet, curtain and the POH option supplement.

Validity

TBM 700B equipped with MOD70-035-001 (Gaseous Oxygen), TBM 700C, TBM 850. SN 346 to 433

SB Reference

SB70-184-25
SB70-175-25



Applicable Not applicable Already applied

Reference to order

T700B252005100000
or T700G252002700000

Estimated labor hours

1 labor hours

**Privacy compartment chemical toilet
electric self-deployment door**

Enjoy the latest enhancement for your TBM



Privacy compartment kit

Complete chemical lavatory compartment including a unique foldable and rigid privacy wall.

Installed by using only 4 screws and a «plug and play» electrical connection type.

The kit also contains:


- a custom made carpet
- leather covered surface will match your interiors
- all the technical documentation

Validity

All TBM Models
From SN 609

SB Reference

SL 70-056-25



Reference to order

Depends on the lower side panel leather color

Estimated labor hours

1 labor hours

Applicable Not applicable Already applied

Garmin G1000 NXi retrofit

Enjoy the latest enhancement for your TBM



G1000 NXi retrofit kit

Latest generation of the Primary Flight Display:
2 GDU 1050A

Latest generation of the Multi-Function Display:
GDU 1550

GCU 475: controller with analog joystick

Flight Stream 510: enabling Database Concierge

Latest software version: v20.51

Pilot's Operating Handbook supplement
(printed copy)

Pilot's guide *(printed copy)*

Optional equipment: GTX 345

Price quote on request from your dealer for the
ADS-B "Out" and "In" transponder solution

Validity

v15.11 installed

SB Reference

SB 70-247-34

940

960

A

930

B

910

C

900

850
G1000

850
Legacy

TBM

Reference to order to Garmin

K10-00029-01

Estimated labor hours

20 labor hours

Applicable Not applicable Already applied

Stick shaker retrofit

Enjoy the latest enhancement for your TBM



Stick shaker kit

Component of the aircraft's stall protection system.

Mechanical actuator compatible with AOA sensor and stall warning sensor.

Warns the pilot in case of imminent stall by actuating vibrations in the pilot control yoke, synchronized with audio alerts.

Validity

SN 434 to 1123

SB Reference

SB 70-238-27

940

960

A

930

B

TBM

Reference to order

OPT70K15900

910

C

900

850
G1000

850
Legacy

Estimated labor hours

8 labor hours

Applicable Not applicable Already applied

MD302 Retrofit

Benefit from the latest enhancement provided for your TBM



MD302 kit

Modern digital standby attitude module to replace traditional electro-mechanical instruments.

Smooth, high-definition graphics

Unique two-screen display with wide viewing angles and a user-friendly menu structure


Two-year or 2,000-hour warranty

Validity

SN 434 to 633, 636 to 644
Without SB70-208-34 applied

SB Reference

SB 70-246-34



Reference to order

OPT70K16100

Estimated labor hours

25 labor hours

Applicable Not applicable Already applied

Clothes hanger installation

Enjoy the latest enhancement for your TBM



Clothes hanger kit

This option involves the installation of two centerline hooks fitted to the luggage compartment's ceiling area, located behind the rear seats.

The installation is more modern and enables coats and other items of apparel to be neatly arranged, keeping them clean and straight.

Validity

SN 434 to 1169

SB Reference


SB70-267-25

Reference to order

OPT70K26700

Estimated labor hours

20 labor hours



Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more “Darth Vader” breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 434 to SN 1215 equipped with MC10 P/N: 10-02-121

Reference

SL70-060-35



Applicable Not applicable Already applied

Reference to order

MC10-02-123 - Qty 2

Strobe and navigation lights update

Benefit from the latest enhancement for your TBM



LED upgrade kit


The new strobes and navigation lights for TBM 700s and TBM 850s offer a longer life, higher efficiency, limited wear-and-tear, enhanced resistance and higher white color temperature.

Daher brings the latest available LED technology in an all-inclusive package.

Validity
From SN 1 to 684

SB Reference

SB70-296-33



Applicable Not applicable Already applied

Reference to order

T700A018404500100 (Red)
T700A018404500200 (Green)

Estimated labor hours

6 hours during an inspection;
7 hours when separate from
an inspection

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours


1 hour during an inspection;
2 hours when separate from
an inspection

TBM
850
+G1000

ELEGANCE & CONVENIENCE

Vapor Cycle Cooling System

Benefit from the latest enhancement for your TBM



System replacement


This replacement for the Vapor Cycle Cooling System is a highly cost-effective alternative to the current system.

Validity

SN 434 to 1407

Reference

SB70-321-21



Applicable Not applicable Already applied

Order reference

OPT70K321-00
1901351
296A32
1601127
1801128
1101317

Estimated labor hours

30 labor hours

TEBM 900

List of special offers:

- Landing gear actuator replacement p.79

List of available retrofits:

- AOA/USP p.80
- AOA/ESP/USP p.81
- Garmin Flight Stream 210 p.82
- Privacy compartment chemical toilet p.83
- Garmin G1000 NXI p.84
- Stick shaker p.85
- Clothes hanger p.86
- Pilot door handle p.87



TBM 900

- MC10 SmartMike® p.88
- LED Ice detection light p.89
- Buckle positioner p.90
- Vapor cycle cooling system p.91



LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



AOA/USP Kit Retrofit

Enjoy flying your TBM with the New E-COPILOT[®] reducing pilot workload



AOA/USP Kit

What the AOA/USP kit bring ?

Enhanced safety with Under-Speed Protection

Modernized avionics with Angle of Attack (AOA) indication via a fully integrated system (PA ON)

Optimize and flight management and the landing approach


Go-around mode with autopilot engaged

Validity
SN 434 to 1105

SB Reference
SB-70-235-34

Reference to order
Parts as per SB

Estimated labor hours
35 labor hours



Applicable Not applicable Already applied

* if GSM 86 P/N 011-01904-03 and GSA P/N 011-00878-20 installed

AOA/USP/ESP Kit Retrofit

Enjoy flying your TBM with the New E-COPILOT[®] reducing pilot workload



AOA/USP/ESP Kit

Enhanced safety with Under-Speed Protection

Modernized avionics with Angle of Attack (AOA) indication via a fully integrated system

Optimize and flight management and the landing approach

Go-around mode with autopilot engaged

Prevent loss of control

Improve safety by deterring aircraft operation outside the desired flight envelope.

Electronic Stability & Protection is active only when the autopilot is disengaged.

940

960

A

Validity

SN 434 to 1105

Reference to order

Parts as per SB

930

B

TBM

910

C

SB Reference

SB-70-235-34

Estimated labor hours

35 labor hours

900

850*
G1000

850
Legacy

Applicable Not applicable Already applied

* if GSM 86 P/N 011-01904-03 and GSA P/N 011-00878-20 installed

Garmin Flight Stream 210

Enjoy the latest enhancement available for your TBM



Compatible with:



Garmin Pilot



ForeFlight Mobile

FS 210 kit

Transfer of your flight plan from your Ipad to G1000

View of your flight info on your Ipad during flight

ADS-B traffic and weather data output to mobile device (US only)

Emergency AHRS included

Validity

SN 434 to 1105
(v15.11 required)

SN 1111 to 1158
except 1142 & 1157
(v6.6 required)

SB Reference


SB70-234-46

Reference to order

Parts as per SB

Estimated labor hours


35 labor hours



Applicable Not applicable Already applied

Privacy compartment chemical toilet electric self-deployment door

Enjoy the latest enhancement for your TBM



Privacy compartment kit

Complete chemical lavatory compartment including a unique foldable and rigid privacy wall.

Installed by using only 4 screws and a «plug and play» electrical connection type.

The kit also contains:


- a custom made carpet
- leather covered surface will match your interiors
- all the technical documentation

Validity

All TBM Models
From SN 609

SB Reference

SL 70-056-25



Reference to order

Depends on the lower
side panel leather color

Estimated labor hours

1 labor hours

Applicable Not applicable Already applied

Garmin G1000 NXi retrofit

Enjoy the latest enhancement for your TBM



G1000 NXi retrofit kit

Latest generation of the Primary Flight Display:
2 GDU 1050A

Latest generation of the Multi-Function Display:
GDU 1550

GCU 475: controller with analog joystick

Flight Stream 510: enabling Database Concierge

Latest software version: v20.51

Pilot's Operating Handbook supplement
(printed copy)

Pilot's guide *(printed copy)*

Optional equipment: GTX 345

Price quote on request from your dealer for the
ADS-B "Out" and "In" transponder solution

Validity

v15.11 installed

SB Reference

SB 70-247-34

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Reference to order to Garmin

K10-00029-01

Estimated labor hours

20 labor hours

Applicable Not applicable Already applied

Stick shaker retrofit

Enjoy the latest enhancement for your TBM



Stick shaker kit

Component of the aircraft's stall protection system.

Mechanical actuator compatible with AOA sensor and stall warning sensor.


Warns the pilot in case of imminent stall by actuating vibrations in the pilot control yoke, synchronized with audio alerts.

Validity

SN 434 to 1123

SB Reference

SB 70-238-27



Applicable Not applicable Already applied

Reference to order

OPT70K15900

Estimated labor hours

8 labor hours

Clothes hanger installation

Enjoy the latest enhancement for your TBM



Clothes hanger kit

This option involves the installation of two centerline hooks fitted to the luggage compartment's ceiling area, located behind the rear seats.


The installation is more modern and enables coats and other items of apparel to be neatly arranged, keeping them clean and straight.

Validity

SN 434 to 1169

SB Reference

SB70-267-25



Reference to order

OPT70K26700

Estimated labor hours

20 labor hours

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Applicable Not applicable Already applied

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more “Darth Vader” breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 434 to SN 1215 equipped with MC10 P/N: 10-02-121

Reference

SL70-060-35



Applicable Not applicable Already applied

Reference to order

MC10-02-123 - Qty 2

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Buckle positioner

Benefit from the latest enhancement for your TBM



Scan to see the video

Buckle positioner kit

The buckle positioner facilitates the proper positioning of the safety belt and harnesses for safety and improved comfort.


Installed at the pilot's seat and the right-hand front seat, it ensures the seatbelt harness can be correctly fastened with the optimal restraint for safety – every time.

Validity

SN 1118 to 1407
(only with AmSafe seatbelts installed)

SB Reference

SB70-302-25



Applicable Not applicable Already applied

Reference to order


T700J25204010000
(Quantity: 2)

Estimated labor hours

1 hour during an inspection;
3 hours out of an inspection

Vapor Cycle Cooling System

Benefit from the latest enhancement for your TBM



System replacement


This replacement for the Vapor Cycle Cooling System is a highly cost-effective alternative to the current system.

Validity

SN 434 to 1407

Reference

SB70-321-21



Applicable Not applicable Already applied

Order reference

OPT70K321-00
1901351
296A32
1601127
1801128
1101317

Estimated labor hours

30 labor hours

TEBM

910

List of special offers:

- Landing gear actuator replacement p.93

List of available retrofits:

- Privacy compartment chemical toilet p.94
- Clothes hanger p.95
- Pilot door handle p.96
- MC10 SmartMike® p.97
- Seatbelt-integrated airbag p.98
- Buckle positioner p.99
- Vapor cycle cooling system p.100

LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3

Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade


- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Privacy compartment chemical toilet electric self-deployment door

Enjoy the latest enhancement for your TBM



Privacy compartment kit

Complete chemical lavatory compartment including a unique foldable and rigid privacy wall.

Installed by using only 4 screws and a «plug and play» electrical connection type.

The kit also contains:


- a custom made carpet
- leather covered surface will match your interiors
- all the technical documentation

Validity

All TBM Models
From SN 609

SB Reference

SL 70-056-25



Reference to order

Depends on the lower side panel leather color

Estimated labor hours

1 labor hours

Clothes hanger installation

Enjoy the latest enhancement for your TBM



Clothes hanger kit

This option involves the installation of two centerline hooks fitted to the luggage compartment's ceiling area, located behind the rear seats.


The installation is more modern and enables coats and other items of apparel to be neatly arranged, keeping them clean and straight.

Validity

SN 434 to 1169

SB Reference

SB70-267-25



Applicable Not applicable Already applied

Reference to order

OPT70K26700

Estimated labor hours

20 labor hours

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more “Darth Vader” breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 434 to SN 1215 equipped with MC10 P/N: 10-02-121

Reference

SL70-060-35



Applicable Not applicable Already applied

Reference to order

MC10-02-123 - Qty 2


Seatbelt-integrated airbag installation

Benefit from the latest enhancement available for your TBM



Seatbelt-integrated airbags

When compared to the standard harness, the airbag system offers improved protection for the pilot and the front right-seat passenger in case of an impact.



Validity

SN 1185 to 1316
not equipped with
MOD70-0388-25

SB Reference

SB70-277-25

Reference to order

Parts as per SB

Estimated labor hours

12 hours during an inspection
14 hours outside an inspection

Applicable Not applicable Already applied

Buckle positioner

Benefit from the latest enhancement for your TBM



Scan to see the video

Buckle positioner kit

The buckle positioner facilitates the proper positioning of the safety belt and harnesses for safety and improved comfort.


Installed at the pilot's seat and the right-hand front seat, it ensures the seatbelt harness can be correctly fastened with the optimal restraint for safety – every time.

Validity

SN 1118 to 1407
(only with AmSafe seatbelts installed)

SB Reference

SB70-302-25



Applicable Not applicable Already applied

Reference to order


T700J25204010000
(Quantity: 2)

Estimated labor hours

1 hour during an inspection;
3 hours out of an inspection

Vapor Cycle Cooling System

Benefit from the latest enhancement for your TBM



System replacement


This replacement for the Vapor Cycle Cooling System is a highly cost-effective alternative to the current system.

Validity

SN 434 to 1407

Reference

SB70-321-21



Applicable Not applicable Already applied

Order reference

OPT70K321-00
1901351
296A32
1601127
1801128
1101317

Estimated labor hours

30 labor hours

TEBM

930

List of special offers:

- Landing gear actuator replacement p.103

List of available retrofits:

- Privacy compartment chemical toilet p.104
- Stick shaker p.105
- Clothes hanger p.106
- Pilot door handle p.107
- MC10 SmartMike® p.108
- Seatbelt-integrated airbag p.109
- GTX 345R transponder p.110
- Complete Garmin G3000 upgrade p.111



TEBM

930

- Garmin Surface Watch update p.112
- Ground clutter suppression for GWX70 p.113
- Garmin Flight Stream 210 p.114
- Garmin Flight Stream 510 p.115
- LED Ice detection light p.116
- Buckle positioner p.117
- Vapor cycle cooling system p.118



LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return

Vs

Overhaul (7 to 10 y.)

\$11,637 each

+ over & above
\$1,000 to \$4,000

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade

- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001



Privacy compartment chemical toilet electric self-deployment door

Enjoy the latest enhancement for your TBM



Privacy compartment kit

Complete chemical lavatory compartment including a unique foldable and rigid privacy wall.

Installed by using only 4 screws and a «plug and play» electrical connection type.

The kit also contains:


- a custom made carpet
- leather covered surface will match your interiors
- all the technical documentation

Validity

All TBM Models
From SN 609

SB Reference

SL 70-056-25



Applicable Not applicable Already applied

Reference to order

Depends on the lower
side panel leather color

Estimated labor hours

1 labor hours

Stick shaker retrofit

Enjoy the latest enhancement for your TBM



Stick shaker kit

Component of the aircraft's stall protection system.

Mechanical actuator compatible with AOA sensor and stall warning sensor.


Warns the pilot in case of imminent stall by actuating vibrations in the pilot control yoke, synchronized with audio alerts.

Validity

SN 434 to 1123

SB Reference

SB 70-238-27



Reference to order

OPT70K15900

Estimated labor hours

8 labor hours

Applicable Not applicable Already applied

Clothes hanger installation

Enjoy the latest enhancement for your TBM



Clothes hanger kit

This option involves the installation of two centerline hooks fitted to the luggage compartment's ceiling area, located behind the rear seats.


The installation is more modern and enables coats and other items of apparel to be neatly arranged, keeping them clean and straight.

Validity

SN 434 to 1169

SB Reference

SB70-267-25



Applicable Not applicable Already applied

Reference to order

OPT70K26700

Estimated labor hours

20 labor hours

Pilot door handle retrofit

Enjoy the latest enhancement for your TBM



Pilot door pushbutton and handle replacement

Is your TBM aircraft giving you “the cold shoulder?”

A new pilot door handle and pushbutton built with carbon composite materials are now available for retrofit on TBM aircraft.

It does not radiate the same sensation of cold as a metallic door handle.


The result: increased comfort during flight, and reduced heat loss.

Validity

Up to SN 1269
equipped with pilot door

SB Reference

SB70-270-52



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

2 labor hours

Oxygen mask MC10 SmartMike® retrofit

Benefit from the latest enhancement for your TBM



A new mask with SmartMike®

For your TBM, it's time for the latest oxygen mask upgrade!

Advantages of the MC10 with SmartMike®


- Improved communications clarity with air traffic control (no more “Darth Vader” breathing sounds)
- Enhanced communications efficiency, including noise reduction function
- Better comfort and lower fatigue
- Less anxiety during situations of stress

Validity

SN 434 to SN 1215 equipped
with MC10 P/N: 10-02-121

Reference

SL70-060-35



Applicable Not applicable Already applied

Reference to order

MC10-02-123 - Qty 2


Seatbelt-integrated airbag installation

Benefit from the latest enhancement available for your TBM



Seatbelt-integrated airbags

When compared to the standard harness, the airbag system offers improved protection for the pilot and the front right-seat passenger in case of an impact.



Validity

SN 1185 to 1316
not equipped with
MOD70-0388-25

SB Reference

SB70-277-25

Reference to order

Parts as per SB

Estimated labor hours

12 hours during an inspection
14 hours outside an inspection

Applicable Not applicable Already applied


GTX 345R transponder

Benefit from the latest enhancement available for your TBM



GTX 345R retrofit kit

With the introduction of the GTX 345R remote-mounted Mode S Extended Squitter (ES) transponder, Garmin provides the ideal upgrade path for aircraft operators looking to satisfy NextGen requirements for ADS-B “Out” — while providing all the weather and traffic benefits of ADS-B “In”



Validity

SN 1111 to 1158
if SB70-282-34 is installed

SB Reference

SB70-284-34

Reference to order

Kit n° OPT70K28400

Estimated labor hours

12 labor hours

Applicable Not applicable Already applied

The complete Garmin G3000 upgrade

Benefit from the latest enhancement for your TBM



G3000 retrofit package

Surface Watch: Provides aural and visual annunciations to help the pilot maintain situational awareness and avoid potential runway incursions.

Turbulence detection: Presents areas of turbulence associated with precipitation and removes ground clutter from the displays.


Flight Stream 510: The Garmin Pilot app and the FS 510 wireless transceiver incorporate an array of features, and replaces the FS 210.

Validity

TBM 930
from S/N 1106 to 1215

SB Reference

SB70-285-34
SB70-286-34
SB70-287-46



Reference to order

OPT70K28200 or
OPT70K28201

Estimated labor hours

3.75 labor hours

SurfaceWatch update

Benefit from the latest enhancement available for your TBM



SurfaceWatch retrofit

The SurfaceWatch feature provides aural and visual annunciations to help the pilot maintain situational awareness and avoid potential runway incursions during ground and air operations in the airport environment.

Runway monitoring technology that prevents pilots from taking off or landing on the wrong runway, a runway that is too short, or a taxiway.

The aircraft must have the G3000 Software version 20.92 installed.

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Validity

TBM 930
from S/N 1106 to 1215

SB Reference

SB70-285-34

Reference to order

P/N 010-00330-5K

Estimated labor hours

0.25 hour during an inspection
1 hour outside an inspection

Applicable Not applicable Already applied

Turbulence detection & Ground clutter suppression for GWX70



Integration of advanced weather radar functions

Garmin Turbulence Detection: presents areas of turbulence associated with precipitation.

Ground Clutter Suppression (GCS): removes ground clutter from the displays.

This option requires G3000 software version 20.92 (or subsequent version) to be installed.

These features also are included in the full G3000 upgrade special offer

Validity

TBM 930
from SN 1106 to 1266

SB Reference

SB70-286-34

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Order reference

P/N 010-00330-F8

Estimated labor hours

0.25 hour during an inspection
1 hour outside an inspection

Applicable Not applicable Already applied

Garmin Flight Stream 210

Enjoy the latest enhancement available for your TBM



Compatible with:



Garmin Pilot



ForeFlight Mobile

FS 210 kit

Transfer of your flight plan from your Ipad to G1000

View of your flight info on your Ipad during flight

ADS-B traffic and weather data output to mobile device (US only)

Emergency AHRS included


Validity

SN 434 to 1105
(v15.11 required)

SN 1111 to 1158
except 1142 & 1157
(v6.6 required)

SB Reference

SB70-234-46



Reference to order

Parts as per SB

Estimated labor hours

35 labor hours

Applicable Not applicable Already applied

Garmin Flight Stream 510

Benefit from the latest enhancement available for your TBM



Flight Stream 510 kit

The Garmin Pilot application and the FS510 wireless transceiver enable an array of features, and replaces the FS210:

Database Concierge: enables wireless transfer of databases to select avionics

Flight Plan Transfer: supports two-way flight plan transmission

Garmin Pilot Interface: provides satellite voice and SMS message capability and delivers audio remote control of Sirius XM audio entertainment

Flight Deck Data Streaming to mobile device


This feature is also included in the complete G3000 upgrade, a special offer containing improvements and a discount.

Validity

TBM 930
from S/N 1106 to 1215

SB Reference

SB70-287-46



Applicable Not applicable Already applied

Reference to order

P/N 011-03595-05

Estimated labor hours

0.25 hour during an inspection
1 hour outside an inspection

LED ice detection light

Benefit from the latest enhancement for your TBM



Ice detection light assembly


For visual detection of wing leading edge ice formation, the latest LED technology is provided in an all-inclusive replacement package.

Advantages of the upgrade include long life, high efficiency, limited wear and tear, better resistance, and a higher white color temperature.

Validity
From SN 1 to 1157

SB Reference

SB70-297-33



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

1 hour during an inspection;
2 hours when separate from
an inspection

Buckle positioner

Benefit from the latest enhancement for your TBM



Scan to see the video

Buckle positioner kit

The buckle positioner facilitates the proper positioning of the safety belt and harnesses for safety and improved comfort.


Installed at the pilot's seat and the right-hand front seat, it ensures the seatbelt harness can be correctly fastened with the optimal restraint for safety – every time.

Validity

SN 1118 to 1407
(only with AmSafe seatbelts installed)

SB Reference

SB70-302-25



Applicable Not applicable Already applied

Reference to order


T700J25204010000
(Quantity: 2)

Estimated labor hours

1 hour during an inspection;
3 hours out of an inspection

Vapor Cycle Cooling System

Benefit from the latest enhancement for your TBM



System replacement


This replacement for the Vapor Cycle Cooling System is a highly cost-effective alternative to the current system.

Validity

SN 434 to 1407

Reference

SB70-321-21



Applicable Not applicable Already applied

Order reference

OPT70K321-00
1901351
296A32
1601127
1801128
1101317

Estimated labor hours

30 labor hours

TEBM 940

List of special offers:

- Landing gear actuator replacement p.120

List of available retrofits:

- Seatbelt-integrated airbag p.121
- Cockpit Pilot Data Link Communication (for U.S. airspace ops. only) p.122
- Cockpit Pilot Data Link Communication (for U.S. and E.U. airspace ops.) p.123
- Buckle positioner p.124
- Privacy compartment chemical toilet p.125
- Vapor cycle cooling system p.126

LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3

Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade

- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001




Seatbelt-integrated airbag installation

Benefit from the latest enhancement available for your TBM



Seatbelt-integrated airbags

When compared to the standard harness, the airbag system offers improved protection for the pilot and the front right-seat passenger in case of an impact.



Validity

SN 1185 to 1316
not equipped with
MOD70-0388-25

SB Reference

SB70-277-25

Reference to order

Parts as per SB

Estimated labor hours

12 hours during an inspection
14 hours outside an inspection

Applicable Not applicable Already applied

Controller-Pilot Data Link Communication *(for U.S. airspace operations only)*

Benefit from the latest enhancement available for your TBM



CPDLC installation kit

The CPDLC's functionality consists of written messages related to flight operations clearances.

It reduces voice radio-frequency congestion and eliminates potential human error in the form of pilot or controller voice misreads.

This helps reduce pilot workload and improves flight safety.

A COM3 functionality is also coming with this upgrade.


NOTE: This installation is for CPDLC communications only in U.S. airspace

Validity

TBM 940
with SN up to 1272

SB Reference

SB70-313-23
SB70-314-34
SB70-315-34



Applicable Not applicable Already applied

Reference to order

Parts as per SB

Estimated labor hours

42.25 labor hours

Controller Pilot Data Link Communication (for U.S. and E.U. airspace operations)

Benefit from the latest enhancement available for your TBM



CPDLC installation kit

The CPDLC's functionality consists of written messages related to flight operations clearances.

It reduces voice radio-frequency congestion and eliminates potential human error in the form of pilot or controller voice misreads.

This helps reduce pilot workload and improves flight safety.


A COM3 functionality is also coming with this upgrade.

Validity

TBM 940
with SN up to 1272

SB Reference

SB70-313-23
SB70-314-34
SB70-315-34



Reference to order

Parts as per SB

Estimated labor hours

42.25 labor hours

Applicable Not applicable Already applied

Buckle positioner

Benefit from the latest enhancement for your TBM



Scan to see the video

Buckle positioner kit

The buckle positioner facilitates the proper positioning of the safety belt and harnesses for safety and improved comfort.


Installed at the pilot's seat and the right-hand front seat, it ensures the seatbelt harness can be correctly fastened with the optimal restraint for safety – every time.

Validity

SN 1118 to 1407
(only with AmSafe
seatbelts installed)

SB Reference

SB70-302-25



Reference to order

T700J252040100000
(Quantity: 2)

Estimated labor hours

1 hour during an inspection;
3 hours out of an inspection

Privacy compartment chemical toilet electric self-deployment door

Enjoy the latest enhancement for your TBM



Privacy compartment kit

Complete chemical lavatory compartment including a unique foldable and rigid privacy wall.

Installed by using only 4 screws and a «plug and play» electrical connection type.

The kit also contains:


- a custom made carpet
- leather covered surface will match your interiors
- all the technical documentation

Validity

All TBM Models
From SN 609

SB Reference

SL 70-056-25



Applicable Not applicable Already applied

Reference to order


Depends on the lower
side panel leather color

Estimated labor hours

1 labor hours

Vapor Cycle Cooling System

Benefit from the latest enhancement for your TBM



System replacement


This replacement for the Vapor Cycle Cooling System is a highly cost-effective alternative to the current system.

Validity

SN 434 to 1407

Reference

SB70-321-21



Applicable Not applicable Already applied

Order reference

OPT70K321-00
1901351
296A32
1601127
1801128
1101317

Estimated labor hours

30 labor hours

TEBM 960

List of special offers:

■ Landing gear actuator replacement

p.128

← MODEL SELECTION

LANDING GEAR ACTUATOR

The overhaul of your actuators is due ?

For a comparable price, replace them with 3 brand new units with an extended 2 year warranty !

P/N to order Qty 3



Special offer

\$13,440 each

2 year warranty

Subject to 4 months pre-order

Core return


Vs

Overhaul (7 to 10 y.)

\$11,637 each

**+ over & above
\$1,000 to \$4,000**

3 months warranty



Benefit from all latest improvement in the product such as:

- More durable locking cage material
- Pressure activated limit switches
- Improved water tightness
- Re-inforced forged bodies

Avoid burden of additional costs and upgrade

- Availability will highly depend on forecast

Purchase includes:

- EASA Dual release
- 2 years warranty
- 10 years to the first overhaul

Available for all the TBM with actuator referenced:

- VSTS081480 / T700A323005000000
- VSTS082315 / T700A323005300000
- VSTS083550 / 7897340002
- VSTS083560 / 7897340001

