

SurfaceWatch update

Benefit from the latest enhancement available for your TBM



SurfaceWatch retrofit

The SurfaceWatch feature provides aural and visual annunciations to help the pilot maintain situational awareness and avoid potential runway incursions during ground and air operations in the airport environment.

Runway monitoring technology that prevents pilots from taking off or landing on the wrong runway, a runway that is too short, or a taxiway.

The aircraft must have the G3000 Software version 20.92 installed.

940

960

A

930

B

TBM

910

C

900

850
G1000

850
Legacy

Validity

TBM 930
from S/N 1106 to 1215

SB Reference

SB70-285-34

Reference to order

P/N 010-00330-5K

Estimated labor hours

0.25 hour during an inspection
1 hour outside an inspection

Applicable Not applicable Already applied